

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Sonora State: Ohio

ZIP: 43701 Country: United States of America

Latitude: 39.989010 Longitude: -81.882717

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/19/2018 Local Time: 1600
mm/dd/yyyy

Time Zone: EST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N23JH

Manufacturer: Mike Toomey

Model: Quickie Q1

Serial Number: 003

Year of Manufacture: 2013

Amateur-Built: ☒ Yes ☐ No If Yes: ☒ Kit/Plans ☐ Original Design Make: Quickie Aircraft Corporation

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 640 lbs

Weight at Time of Accident/Incident: 500 lbs

Number of Seats: 1 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 0

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☒ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☒ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Onan				18	99.4	2	
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☒ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: 07/04/2018
mm/dd/yyyy

Airframe Total Time: 99.4 hrs

hours measured at (Select one)

- ☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☒ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☐ Yes ☒ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☐ Yes ☐ No

Was ELT still connected to antenna? ☐ Yes ☐ No

Did ELT Activate? ☐ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☒ Other, Specify: Pannel supported iPad with ForeFlight (phone as backup)

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Jacob Philip HavensCity: FindlayState: Ohio ZIP: 45840Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: United States of America**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Zanesville AirportDistance From Airport Center: 3 smAirport Identifier: KZZVDirection From Airport: 005 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 899 ft. msl**Runway Information**Runway ID: 16 (L/R/C) Length: 5000 ft Width: 150 ft**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touch down)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☒ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☒ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

“Flight Crewmember 1” Responsibilities at the Time of Accident/Incident

☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

“Flight Crewmember 1” Identification

First Name: Jacob City of Residence: Findlay

Middle Initial: P State: Ohio ZIP: 45840

Last Name: Havens Country: United States of America

Age at time of Accident/Incident: 24 Date of Birth: mm/dd/yyyy

Certificate Number:

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious		Seat Occupied ☐ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☒ Center ☐ Single		Restraint Type Available ☐ None ☐ Lap only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☐ Flight Instructor ☒ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer						
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☒ Class 2 ☐ Unknown			Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance		Date of Last Medical <u>03/16/2018</u> <i>mm/dd/yyyy</i>

Medical Certificate Limitations

N/A

Medical Certificate Special Issuance

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:	Flight Review Aircraft
<u>03/30/2018</u> <i>mm/dd/yyyy</i>	Make: <u>Cirrus</u> Model: <u>SR-22</u>

Airplane Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Single-Engine Land ☒ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
--	--	---	--

Type Ratings	Student Endorsements <i>(Include dates)</i>

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	586	45	516	61	37	44	65		3.7	
Pilot in Command (PIC)	430	45	400	28	28	44	65			
Time as Instructor										
This Make/Model										
Last 90 Days	46	20	46							
Last 30 Days	10	5	10							
Last 24 Hours	3	3	3							

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available	Used
☐ None	☐ None
☐ Lap only	☐ Lap only
☐ 3-point	☐ 3-point
☐ 4-point	☐ 4-point
☐ 5-point	☐ 5-point
☐ Unknown	☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: KZZV
 City: Zanesville
 State: Ohio
 Country: USA

Time of Departure

Time: 1530
 Time Zone: EST

Destination

Airport ID: KZZV
 City: Zanesville
 State: Ohio
 Country: USA

Type Flight Plan Filed

☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR
 Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☒ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

1900 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☒ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☐ On-Board Weather

Weather Observation Facility

Facility ID: _____
 Observation Time: _____
 Time Zone: _____
 Distance from Accident Site: _____ nm
 Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☒ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

5000 ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or 80 (F)

Dew Point: _____ (C) or 65 (F)

Altimeter Setting: 30.00 in. Hg
 or _____ MB

Wind Direction

☐ Variable

-or-
 Direction: _____ degrees true

Wind Speed

☐ Calm
☒ Light and Variable

-or-
 Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
 Speed: _____ kts

Visibility 10+ miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount Type
☒ None ☒ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount Type
☒ None ☒ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply) Severity
☐ None ☒ Light
☐ Clear Air ☐ Moderate
☒ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

N/A

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Exterior fiberglass cracks along fuselage and wing root. Spar and control surfaces are okay. Firewall and forward severely damaged from impact. Broken exhaust is suspect to engine failure and appears to have happened before the impact.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Writeup of day's activities attached in a separate document.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

I was planning on installing stronger exhaust manifolds after the summer season because I wanted to take the aircraft to Oshkosh. I should have grounded the airplane when this same exhaust manifold broke previously.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

I had a previous break of the right exause manifold. This was removed, welded back together and reinstalled until a stronger set could be fabricated. This failed again in flight and is suspect as the cause of the incident.

**Total Time/Cycles
On Part**

99.4 Hours

Cycles

**Time Since This Part
Inspected/Overhauled**

2 Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

6.5 Gallons

Fuel Type☐ 80/87☐ 115/145☐ Jet B☒ Other, specify 91 Ethnol Free☐ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Aircraft had to be lifted off of the pilot who was trapped inside the cockpit after coming to rest upsidedown.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number****Manufacturer:** _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report08/05/2018*mm/dd/yyyy***Name of Pilot/Operator:** Jacob Havens**Signature:** _____*-- or --*

Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report**Name:** _____**Title:** _____**Signature:** _____*-- or --*

Check here to electronically sign this document

FOR NTSB USE ONLY**NTSB Accident/Incident No.**

CEN18LA284

Reviewed by NTSB Regional Office

Denver, CO

Name of Investigator

Edward Malinowski

Date Report Received

8/5/18

N23JH Forced Landing

By: Jacob Havens

Thursday, July 19th, was a beautiful day to fly. Winds were light out of the northeast and few clouds were floating by at 5000 feet. I was excited for the day because for the first time in eight months of owning my Quickie Q1, this would be my first air-to-air photo shoot. The plan was simple, visit my friends in Zanesville, Ohio, do some flying and come home to see my friends in Cincinnati that night! Little did I know this perfect day to fly would be my most challenging.

Starting around 9:00am, I got ready for the day, drove to the airport and made my typical smoothie run when I head to this side of town. The airport is about 45 minutes away from me so I had time to think about the new battery I had just purchased and how this might affect my experimental plane.

The day prior, I was with the airplane to do some spot landing in preparation for Oshkosh but was grounded due to a dead battery. This plane is always hand propped, but requires a charge to operate the spark plugs' igniter, rather than an engine driven spark from a magneto. So I charged the battery with jumper cables and was able to start the aircraft. Before flying again, I decided to call it a day and remove the battery. I ended by disassembling the aircraft to remove the battery and purchased the new one later that night.

So after my smoothie, I installed the new battery, tested the connections and found 13-14 volts versus the previous days 8.5-9.5 volts. With the new batteries ready to go, I reinstalled the tail section of the aircraft and cycled the engine through an engine run.

Feeling confident with the performance of the aircraft - and trying to stick to my commitment of arriving in Zanesville around 1:00pm – I jumped in and taxied out to runway 11. My takeoff, flight and landing were uneventful all the way to Zanesville; with an arrival just after 1:00pm to boot. The only abnormal part of this trip was my left roll tendency due to a newly installed Go Pro on the canard just above my left main tire. The camera did not perform well and was subjected to constant vibrations, which cracked the housing and caused the mount to fail while taxiing into parking.

With 1.6 hours and a new landing in the logbook, I met up with Nick and Tony of Zanesville Aviation to catch up and prepare for our photo mission. Seeing that the Stinson (our second aircraft for the day) needed some fuel, I rode along as Nick made the short flight up to the Richard Downing airport. I stayed with the aircraft while Nick got everything loaded up and then rode along for the return back to Zanesville. On the way back, I spent my time playing with the camera I brought for the photo flight to adjust the settings as best I could.

Once back at Zanesville, we discussed the photo flight and decided that Tony would fly, Nick would take pictures and I would position the quickie off of the right wing. We would meet north of the field where the terrain of rolling hills and wooded areas would provide the best backdrop for a northbound photo run, standard rate 180 and then return southbound to the airport. All in all, this flight should only take about 30 minutes to complete.

After a quick walk around and easy startup, I taxied out to runway 16 and took off with a climbing left turnout to head north. Upon reaching 2,500ft (about

1,500 AGL), I joined up with Nick and Tony for the mission. Everything went great and we were able to keep a nice formation while Nick captured some great pictures of the Quickie and me.

At the end of the flight, we decided to head back to the airport and I gave a rudder wag to Nick and Tony for a job well done. Immediately after, my power setting dropped by over 1000rpm (3700rpm → 2600rpm) and began pulling with about twice the fuel (1.8gph → 3.0gph). I was able to maintain my current airspeed (about 80mph) and altitude (about 1000ft agl) so I announced that I was having engine trouble and was planning a strait in for runway 16. When this started, I was approximately 4 miles north of the airport and noticed Interstate 70 close to the airport that I planned to use if I could not make the field. A moment after announcing my intentions, my rpm setting began to drop even further. Losing a steady 20-rpm per second I knew I would not be able to make the airport. Seeing a neighborhood between I-70 and my current position - now about 3 miles from the airport - I looked right, saw a forest and looked left to see a dogleg of a road pointed into the wind with fields beyond it. Seeing this as my best option, I told Nick my intentions over the Zanesville Unicom frequency and began a descending right turn down to the road. Narrowly missing some trees and not spotting any traffic, I lined up for the road with too much energy and although inches from the ground, knew I could not stop in time.

Noticing signs at the turn of this road, I decided to ask the engine for all the power I could and go over these signs. Luckily there was enough to get over the obstacles and across a large drainage area. Seeing only cornfields in front of me, I

though to myself, “okay, it’s really happening,” chopped the power and flew above the top of the corn bleeding off as much airspeed as possible before dropping in.

The crash felt abrupt and sudden, I have a very distinct memory of the canard splaying corn out in front of me and watching the nose strike the ground. This happened while traveling about 45mph and affected less than 100ft of corn. The momentum and angle of the crash caused the tail of the aircraft to gently continue over before coming to rest upside down with me trapped inside the cockpit. The canopy had shattered around me. After unhooking from my harness; I was unable to get out of the wreck. I checked myself and couldn’t believe nothing on me was broken... my shoulders hurt from the harness, I had cuts on my hands from holding the control surfaces and goose eggs on my knees from hitting the panel, but I was okay! It was at this point; I noticed fuel leaking from the vent on the cap of the tank and my electrical system still on. I secured the aircraft as best I could and then shouted for “Siri” to call Nick. I was only able to talk to him briefly before getting disconnected but he knew I was okay.

My next phone call was with Jen at 911, the call lasted about 30 minutes and she stayed on the line until the EMS team was able to locate me in the cornfield. At only 300lbs, the plane was not too hard to pull off of me and flip over to stop the leaking and free me from the wreckage. Nick and Tony were with the search team and after statements with the press, local and state officials, they offered to fly me home to Cincinnati in a 182RG.

Of course I took them up on this chance to get back up in the air! I wanted to get back up before I had a chance to get nervous. So, from the right seat, I flew the 3

of us to Cincinnati for dinner. We discussed my plans to drive up with a trailer the next day and recover the plane and they took off for the night.

This was my first full day of flying the Quickie after its conditional inspection so I was caught off guard to say the least. During the inspection, a cracked exhaust manifold had been welded back together and reinstalled. Upon inspection of the wreckage, finding the same exhaust broken in a different spot seems to be the cause of my initial power loss. This break happened directly under the fresh air intake for the engine and the recycled air forced a rich mixture and initial rpm drop. I believe the vibrations of the broken exhaust then knocked my carburetors mixture screw loose and caused the steady rpm drop as it unscrewed. The combination of these items is still under review and will be inspected by the FAA in the coming week.