

New Carburettor icing-probability chart


To work out dew point depression:

$$\text{Temp} \text{ Minus } \text{Dew Pt.} = \text{Dew Pt. Depression}$$

To use this chart:

- obtain the temperature and dew point
- calculate the difference between the two. This is the 'dew point depression'
- for example, if the temperature is 12° C ① and the dew point is 2° the dew point depression will be 10° ②
- for icing probability, refer to the shading legend appropriate to the intersection of the lines ③
- for relative humidity, refer to the right hand scale ④

-  Serious icing – any power
-  Moderate icing – cruise power; Serious icing – descent power
-  Serious icing – descent power
-  Light icing – cruise or descent power



KZZV 191953Z AUTO 11007KT 10SM CLR 28/13 A3003 RMK AO2 SLP163 T02780128=