



Photo 1 – View of the helicopter at the accident site (courtesy of the Texas Renaissance Festival).



Photo 2 – View of the left side of the helicopter.



Photo 3 – View of the right side of the helicopter.



Photo 4 – View of the engine.



Photo 5 – View of the main rotor blades.



Photo 6 – View of the left seat anti-torque pedals.




Photo 7 – View of the tail rotor servo being bench tested (courtesy of Helicopter Accessory Service Inc.).