

8-6-18

Departed runway 18 headed south towards the field-rye & turnip seeds.

On 2nd ag pass north bound it pulled up at which time it felt a loss of power.

It immediately pushed power full forward & pushed in on mixture - with no results it dumped the load and located the best landing site. It pitched for best glide speed fell short striking a tree just shy of the target. After impacting the tree the airplane spun to the right.

It pulled control stick back and kicked left rudder to keep plane up right. impacted ground at front right location.

It crawled out removed helmet and walked to the nearby house to seek help.

Sought medical attention at the local hospital in Marshall Mo.

I did not seek medical attention because I was not hurt bad.

08/07/2018 12:47