



Photo 1 – Airplane at Accident Site



Photo 2 – Substantial Damage to Left Horizontal Stabilizer