

Communication Summary

September 20, 2018

Information from: Inspector Bret Proud, DEN FSDO



Summary & Factual Information: Inspector Proud was asked to conduct an examination of N8003W and see if its engine would run. The accident airplane's engine started and ran in the field where it had come to rest.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator