



RECORD OF INFORMATION

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN18LA392

The FAA inspector assigned to the accident provided the following information:

- The work order to replace the No.1 cylinder o-ring was dated 9/27/2018.
 - Work order # 201331 A/C TSN 1330.0, Engine TT1330.0, Hobbs 1330.0
- The pre-buy inspection was the last maintenance that occurred to the engine prior to the accident.
- The maintenance provider did not follow manufacture's manual as far as removing and replacing components.