



NATIONAL TRANSPORTATION SAFETY BOARD
Central Region
Denver, Colorado

Investigator's Statement

CEN19FA093
Greeley, Colorado

Examination Observers:

Jennifer Rodi – NTSB, CRA – Denver, Colorado

During the examination the following observations were made:

- The ELT was turned on and 121.5 was monitored with no tone noted.
- The ELT was disassembled and it was verified that the batteries were installed correctly. The ELT was reassembled and tested again with no change in the result.
- The ELT was disassembled and the batteries were replaced with new batteries. The ELT was reassembled and tested again and a brief/faint chirp was heard.
- The ELT was connected to an antenna and there was nothing further heard from the ELT.



Figure 1. Emergency Locator Transmitter