



Customer Services
Piper Aircraft Corporation

SERVICE LETTER

No. 590

Lock Haven, Pennsylvania, U.S.A.

May 25, 1972

Subject: Fuel Selector Valve Cover Replacement

Models and Serial Numbers Affected:

Models Affected

PA-28-140 Cherokee
PA-28-150, PA-28-160, PA-28-180
Cherokee
PA-28R-180 Cherokee Arrow
PA-28R-200 Cherokee Arrow

Serial Numbers Affected

28-20000 to 28-26946 incl.
28-01 to 28-5859 incl.
28R-30000 to 28R-31270 incl.
28R-35001 to 28R-35820 incl.

Compliance Time: Recommended at the next 100 hour or annual inspection period, whichever occurs first.

Purpose: To announce the availability of a new fuel selector valve cover assembly and mating handle, which reduces the possibility of pilot mismanagement of the fuel system through inadvertent selection to the "OFF" position.

Instructions: Contained in Piper Kit No. 760 546V, Fuel Selector Valve Cover Replacement.

Material Required: One (1) each (per aircraft) Kit No. 760 546V, Fuel Selector Valve Cover Replacement, at a suggested retail unit price of \$14.48.

Availability of Parts: Your Piper Dealer.

Effectivity Date: This Service Letter is effective June 9, 1972.

Summary: Please contact your Piper Dealer to make arrangements for the installation of this product advancement item on your aircraft. Material cost is specified above, and the labor required for this modification constitutes approximately one-half hour per aircraft.