



RECORD OF CORRESPONDENCE

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN19FA185

Multiple airport personnel stated that due to several lakes near BRD, patchy fog and visibility conditions could vary significantly at different locations on the airport. As an example, one end of a runway might be clear of clouds, whereas the other end of the runway would be very thick fog.