

DATE	TIME	TIME IN SERVICE	Inspections, Tests, Repairs and Alterations
			Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Airframe

DATE: 1/11/19 MODEL: 95-B55 (T42A) ACTT: 5514.8 HOBBS: 703.0
REG: N8910U S/N: TC-946

- 1 C/W AD 76-07-12 R1 BY OPERATIONAL CHECK OF BENDIX IGNITION SWITCH.
 - 2 AD 90-08-14 WING SPAR INSPECTION NOT DUE AT THIS TIME. DUE AT HOBBS: 950.0.
 - 3 C/W AD 2007-08-08 BY LUBRICATION OF LANDING GEAR UPLOCK ROLLERS.
 - 4 INSTALL NEW FELT ON NOSE GEAR P/N: 154-00600.
 - 5 INSTALL NEW LEFT AND RIGHT BRAKE DISCS P/N: 164-02706 AND 8 NEW LININGS P/N: 066-09700.
 - 6 INSPECTED ELT IN ACCORDANCE WITH FAR 91.207(D) **DUE JANUARY 2020.**
- **PITOT / STATIC NEXT DUE: DECEMBER 2019.**

PAGE 1 OF 2

STEPHEN STEWART - A&P

PERTINENT DETAILS ON FILE: W.O. 891011119

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Airframe

DATE: 1/11/19 MODEL: 95-B55 (T42A) ACTT: 5514.8 HOBBS: 703.0
REG: N8910U S/N: TC-946

- 7 ADJUST LEFT AND RIGHT MAIN GEAR INNER DOORS.
- 8 INSTALL RIVETS IN RIGHT WING WELL AT WING ROOT P/NS: CR3213-4-4 AND CR3213-4-6.
- 9 INSTALL NEW RIGHT COWLING INBOARD DOOR HINGE P/N: 50-980000-4.
- 10 INSTALL NEW LEFT AND RIGHT INBOARD MAIN GEAR WHEEL BEARINGS P/N: 13889 AND RACE P/N: 13836.
- 11 REMOVE AND REINSTALL NOSE GEAR ASSEMBLY BRACE AFTER INSTALL OF THE FOLLOWING NEW NOSE GEAR BUSHING P/N: 35-820115, 1 NEW NOSE GEAR SHIM P/N: 35-820134, AND 1 NEW SHIMMY DAMPENER BOLT P/N: AN3-5.
- 12 INSTALL NEW MAIN GEAR PARTS: 2 NEW BOLTS ON MAIN GEAR UPLOCK ROLLER P/N: 130909B265, 2 NEW MAIN GEAR DRAG BRACE BOLTS P/N: 35-815274-1, 2 NEW BUSHINGS ON MAIN GEAR UPLOCK ROLLER P/N: 35-810122-1, 2 NEW BUSHINGS ON MAIN GEAR BRACE END P/N: 35-815124.
- 13 SERVICE WITH 5606 HYDRAULIC FLUID AND NITROGEN.

PAGE 2 OF 2

CHRISTIAN MUNOZ - A&P

PERTINENT DETAILS ON FILE: W.O. 891011119

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------	---------------------------	------------------	-----------------------------	---



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Airframe

DATE: 1/11/19 MODEL: 95-B55 (T42A) ACTT: 5514.8 HOBBS: 703.0
REG: N8910U S/N: TC-946

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND C/W
OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE
WITH ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA 2

PERTINENT DETAILS ON FILE: W.O. 891011119

Engine Record General Information

Manufacturer Continental

Model IO-470-L

Serial CS 192877-R

Type Certificate _____

This engine is currently installed in aircraft: _____

Beech Baron B55

TC-946

N8910U

Minimum Octane Fuel _____

Oil Grade Summer _____

Winter _____

Magneto Time _____

Point Setting _____

Firing Order _____

Spark Plug Gap _____

Manufacturer's Recommended Overhaul at _____ hours

Engine - Right
Log Book #2
from Oct. 7, 2003

DATE

TIME

SERVICE

Technician or Repair Facility. (See back pages for other specific entries.)



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Right Engine

DATE: 1/11/19

MODEL: IO-470-L

SMOH: 1470.7

HOBBS: 703.0

REG: N8910U

S/N: CS192877-R

- 1 COMPRESSION TEST: 1/72, 2/60, 3/70, 4/60, 5/60, 6/58.
- 2 INSTALL NEW AIR FILTER ELEMENT P/N: BA7605.

STEPHEN STEWART - A&P

PERTINENT DETAILS ON FILE: W.O. 891011119



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Right Engine

DATE: 1/11/19

MODEL: IO-470-L

SMOH: 1470.7

HOBBS: 703.0

REG: N8910U

S/N: CS192877-R

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND C/W OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS ENGINE WAS INSPECTED IN ACCORDANCE WITH ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA

PERTINENT DETAILS ON FILE: W.O. 891011119

R E	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------	------------------------------------	---------------------------	--------------------------------------	---

wo: WO_65

Engine R - page 1 of 1



Barron Aircraft Maintenance · 2290 Becker Blvd · Santa Rosa, Ca 95403 · 707-284-9786



N8910U
Hobbs: 708.6

May 16, 2019

1. Drained oil, Removed Cut and inspected oil filter. Removed, inspected and reinstalled bottom spark plugs.serviced with 11Qts of W100. Installed new oil filter. Installed (12) W100 - Oil, Installed (2) AA48109 - Oil Filter, Installed (5) M674 - Spark Plug Gaskets.

With respect to the work performed, this engine r is approved for return to service. Details of work performed are on file with Barron Aircraft Maintenance under work order: WO_65.

Bryston Brauer A & P



Engine Record General Information

|| Engine - Left ||
Log Book #2
from Oct. 7, 2003 ||

Manufacturer Beechcraft

Model B55

Serial TC-946

Type Certificate N8910U

This engine is currently installed in aircraft: _____

Minimum Octane Fuel _____

Oil Grade Summer _____

Winter _____

Magneto Time _____

Point Setting _____

Firing Order _____

Spark Plug Gap _____

Manufacturer's Recommended Overhaul at _____ hours

Continental IO-470-L

Serial No. CS 192677-72-L-R

DATE

TIME

SERVICE

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)

BARRON AIR, 2290 BECKER BLVD, SANTA ROSA, CA 95403
TEL (707) 284-9786 Date 7/16/2018 Hobbs 691

Changed oil and filter, service with 10 Qts AeroShell W100
Function test normal.

David R Barron A&P [REDACTED]



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Left Engine

DATE: 1/11/19

MODEL: IO-470-L

SMOH: 1470.7

HOBBS: 703.0

REG: N8910U

S/N: CS192677-72-L-R

- 1 COMPRESSION TEST: 1/65, 2/64, 3/60, 4/68, 5/50, 6/68.
- 2 INSTALL NEW AIR FILTER ELEMENT P/N: BA7605.

[REDACTED]
STEPHEN STEWART - A&P [REDACTED]

PERTINENT DETAILS ON FILE: W.O. 891011119

TIME

SERVICE

Technician or Repair Facility. (See back pages for other specific entries.)

9519 Airport Drive, Hanger 19
Visalia, CA 93277**Left Engine**

DATE: 1/11/19

MODEL: IO-470-L

SMOH: 1470.7

HOBBS: 703.0

REG: N8910U

S/N: CS192677-72-L-R

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND C/W OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS ENGINE WAS INSPECTED IN ACCORDANCE WITH **ANNUAL** INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA

PERTINENT DETAILS ON FILE: W.O. 891011119

Barron Aircraft Maintenance · 2290 Becker Blvd · Santa Rosa, Ca 95403 · 707-284-9786

N8910U

May 16, 2019

Hobbs: 708.6

1. Drained oil, Removed Cut and inspected oil filter. Removed, inspected and reinstalled bottom spark plugs.serviced with 11Qts of W100. Installed new oil filter. Installed (12) W100 - Oil, Installed (2) AA48109 - Oil Filter, Installed (5) M674 - Spark Plug Gaskets.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Barron Aircraft Maintenance under work order: WO_65.

Bryston Brauer A & P

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
7/16/18	Hobbs 691.0	0	Installed on N8910U R+side	[Redacted]
 AMS AIRCRAFT MECHANICAL SERVICES, Inc. 9519 Airport Drive, Hanger 19 Visalia, CA 93277 <u>Right Propeller</u> DATE: 1/11/19 MODEL: 2AF34C55-NO HOBBS: 703.0 REG: N8910U S/N: 730814 695613 ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND C/W OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS PROPELLER WAS INSPECTED IN ACCORDANCE WITH <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. APPROVED FOR RETURN TO SERVICE. [Signature] STEPHEN STEWART - IA [Redacted] PERTINENT DETAILS ON FILE: W.O. 891011119				

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Left Propeller

DATE: 12/22/17 MODEL: 2AF34C55-JMO
REG: N8910U S/N: 691971

HOBBS: 669.0

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND C/W
OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS PROPELLER WAS INSPECTED IN ACCORDANCE
WITH **ANNUAL** INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA

PERTINENT DETAILS ON FILE: W.O. 891122217



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Left Propeller

DATE: 1/11/19 MODEL: 2AF34C55-JMO
REG: N8910U S/N: 691971

HOBBS: 703.0

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND C/W
OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS PROPELLER WAS INSPECTED IN ACCORDANCE
WITH **ANNUAL** INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA

PERTINENT DETAILS ON FILE: W.O. 891011119