



MEMORANDUM FOR RECORD

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN19FA238

An autopsy of the flight instructor and student pilot was performed by Southwestern Institute of Forensic Sciences, Dallas, Texas. The cause of death of the flight instructor was thermal burns. The cause of death of the student pilot was smoke inhalation and thermal burns.