

SN100867K

PROPELLER LOG BOOK



SENSENICH PROPELLER MFG. CO.

Lititz, Pennsylvania 17543

Internet: <http://www.sensenich.com>.

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

PROPELLER MAINTENANCE RECORD

PROPELLER MODEL 76 Em 8~~5~~50-60
 PROPELLER SERIAL NUMBER 100867K




TABLE OF PROPELLER ATTACHING BOLT WRENCH TORQUE
 Sensenich Metal Propellers (the proper torque is also shown on Blade Information Decal)

PROPELLER SERIES**	BOLT DIA. (inches)	RECOMMENDED WRENCH TORQUE		
		ln.-lb.	ft.-lb.	n.-m.
69CK, M69CK (6 bolts) 72CK (6 bolts) 74CK, M74CK (6 bolts) 76AK, M76AK (6 bolts) 76AM6, M76AM (6 bolts) 74DM6, M74DM (6 bolts) 74DR, M74DR (8 bolts)	$\frac{3}{8}$ (0.375)	280-300	23-25	32-34
74DM7 (6 bolts)	$\frac{7}{16}$ (0.4375)	480-540	40-45	54-61
72CC, 72FM8 (6 bolts) 74DC, M74DC (6 bolts) 76EM8, M76EMM (6 bolts) * 80BM8, M80BMM (bolts)	$\frac{1}{2}$ (0.500)	720-780	60-65	81-88

* Not in production

** These are the basic propeller models. Spacer addition does not affect recommended wrench torque.

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10-17-2008		This propeller assembly has been installed on N1567L S/N: 28-4463 @ aircraft Hobbs: 1212.6. Reference W.O. 13409 for details.	 Worldwide Aircraft Services, Inc. CR# 
		April 10, 2009 Tach: 2680.28 Hobbs: 1219.7 Spoh: 7.1	
		Performed an Annual inspection IAW FAR part 43, appendix D. Filed nicks and painted blades. I certify this Propeller to be in an airworthy condition.	
			
		Michael F. Strickland A&P  IA	
May 12, 2010	2719.0	cur Annual inspection IAW FAR 43 Appendix D (h)	 

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-8-11	2854.6	Annual inspection	[REDACTED]
5-3-12	2978.0	Annual inspection	AEP [REDACTED] IA
6-23-15		Annual inspection	[REDACTED]

Inspected propeller, spinner and back plate. I certify that this propeller has been inspected in accordance with a 100hr/annual inspection and was determined to be in an airworthy condition.

Kurt Leaders IA [REDACTED] 4/15/17, Tach 3300, SPOH 626.82

3-27-18
Inspected propeller. I certify this propeller has been inspected
I.A.W. 100 Hr/annual inspection & has been determined airworthy
AT this time. [REDACTED] BRIAN J. JOHNSON AEP. [REDACTED] IA.
Tach: 3467.47
Hobbs: 2058.5

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

[illegible]