



Memo for Record

Craig Hatch
Air Safety Investigator
Central Region

NTSB Accident Number: CEN19LA055, NTSB Material Lab Report No. 20-013

Narrative: Per conversation with Lycoming Engines representative:

- The No. 3 Main journal was misidentified in the report, and should read; No. 4 Main bearing journal.