




Photo 1 – Oil Pressure Switch

Photo courtesy of Continental



Photo 2 – Oil Pressure Switch with heat damage

Photo courtesy of Continental



Photo 3 - Threaded end of oil pressure switch

Photo courtesy of Continental