

Vine Grove Airport
Vine Grove, Kentucky, USA
FAA Identifier: 70KY
Lat/Long: 37-48-57.2420N / 085-57-52.8670W
37-48.954033N / 085-57.881117W
37.8159006 / -85.9646853 (estimated)
Elevation: 680 ft. / 207.3 m (surveyed)
Variation: 02W (1985)
From city: 1 mile NE of VINE GROVE, KY
Time zone: UTC -4 (UTC -5 during Standard Time)
Zip code: 40175

Godman Army Airfield
Fort Knox, Kentucky, USA
FAA Identifier: FTK
Lat/Long: 37-54-26.0000N / 085-58-17.6000W
37-54.433333N / 085-58.293333W
37.9072222 / -85.9715556 (estimated)
Elevation: 754.3 ft. / 229.9 m (surveyed)
Variation: 03W (1995)
From city: 1 mile W of FORT KNOX, KY
Time zone: UTC -4 (UTC -5 during Standard Time)
Zip code: 40121

KFTK, Fort Knox (United States)
WMO index: 72424
Latitude 37-54N. Longitude 085-58W. Altitude 230 m.
#####

METAR/SPECI from KFTK

201906242158 METAR KFTK 242158Z 25013G18KT 10SM SCT028 26/19 A2980 RMK
A02A SLP088 T02550187 \$=
201906242058 METAR KFTK 242058Z 23012KT 10SM SCT020 25/20 A2980 RMK A02A
SLP088 60017 T02460198 \$=
201906242036 SPECI KFTK 242036Z 25009KT 10SM BKN015 25/21 A2979 RMK A02A
SLP085 \$=
201906241956 METAR KFTK 241956Z 26011G19KT 10SM BKN010 24/21 A2979 RMK
A02A SLP085 T02380211 \$=
201906241855 METAR KFTK 241855Z 25013G18KT 10SM BKN007 BKN030 22/22 A2978
RMK A02A SLP082 P0018 T02200220 \$=
201906241830 SPECI KFTK 241830Z 27012G17KT 3SM -RA BR OVC008 22/22 A2977
RMK A02A SLP079 \$=

201906241804 METAR KFTK 241804Z 24009KT 1SM RA BR OVC005 22/22 A2975 RMK
 SLP071 P0007 T02220222 \$=
 201906241756 METAR KFTK 241756Z 14008KT 3SM -RA BR BKN005 OVC012 22/22
 A2974 RMK SLP068 P0005 60012 T02230223
 10225 20212 57030 \$=
 201906241726 SPECI KFTK 241726Z 14007KT 4SM -RA BKN005 OVC012 22/22 A2975
 RMK SLP071 \$=
 201906241719 SPECI KFTK 241719Z 12009KT 3SM -RA BR BKN012 OVC020 22/22
 A2975 RMK SLP071 \$=
 201906241656 METAR KFTK 241656Z 10009KT 10SM SCT012 OVC020 22/22 A2976
 RMK RAE47 SLP075 P0004 T02200220
 \$=
 201906241624 SPECI KFTK 241624Z 11006KT 5SM -RA SCT012 OVC025 22/22 A2979
 RMK SLP085 \$=
 201906241555 METAR KFTK 241555Z 00000KT 4SM -RA SCT008 OVC012 21/21 A2981
 RMK SLP092 P0002 T02120212 \$=
 201906241524 SPECI KFTK 241524Z 21004KT 4SM -SHRA SCT010 OVC020 22/21
 A2983 RMK SLP099 \$=
 201906241458 METAR KFTK 241458Z 21006KT 10SM -RA FEW010 BKN020 OVC040
 22/21 A2983 RMK SLP099 P0000 60001
 T02180209 58004 \$=
 201906241356 METAR KFTK 241356Z 21006KT 10SM FEW008 BKN030 BKN150 OVC200
 22/21 A2985 RMK SLP105 P0001 \$=
 201906241340 SPECI KFTK 241340Z 20008KT 10SM BKN030 OVC200 22/21 A2985
 RMK RAB1232RAE35 \$=
 201906241255 METAR KFTK 241255Z 21009KT 10SM -RA FEW010 BKN030 BKN200
 22/21 A2985 RMK SLP105 P0000 \$=
 201906241232 SPECI KFTK 241232Z 21010KT 10SM -RA FEW030 SCT080 BKN120
 BKN200 22/20 A2986 RMK \$=
 201906241155 METAR KFTK 241155Z 22011KT 10SM SCT080 BKN120 BKN200 22/21
 A2984 RMK SLP102 70004 52011 \$=
 201906241057 METAR KFTK 241057Z 20006KT 10SM BKN120 BKN150 BKN200 20/20
 A2984 RMK SLP103 \$=
 201906240956 METAR KFTK 240956Z 22004KT 10SM FEW120 FEW200 20/20 A2981
 RMK SLP092 \$=
 201906240856 METAR KFTK 240856Z AUTO 17007KT 10SM M 20/20 A2981 RMK A02
 SLP092 T01990199 58010 CHINO RWY36
 \$=
 201906240836 SPECI KFTK 240836Z AUTO 17004KT 10SM M 20/20 A2981 RMK A02
 SLP091 CHINO RWY36 \$=
 201906240756 METAR KFTK 240756Z AUTO 21005KT 10SM M 20/20 A2983 RMK A02
 SLP097 T02030203 CHINO RWY36 \$=
 201906240656 METAR KFTK 240656Z AUTO 20007KT 10SM M 21/21 A2984 RMK A02
 SLP101 T02110211 CHINO RWY36 \$=
 201906240556 METAR KFTK 240556Z AUTO 18007KT 10SM M 21/21 A2984 RMK A02
 SLP101 60004 T02140214 10238 20214
 58001 CHINO RWY36 \$=
 201906240456 METAR KFTK 240456Z AUTO 19010KT 10SM M 22/22 A2984 RMK A02
 RAB17E23DZB23E32 SLP101 P0000 T02170215

403020193 CHINO RWY36 \$=
 201906240432 SPECI KFTK 240432Z AUTO 18012G17KT 10SM M 22/22 A2985 RMK
 A02 RAB17E23DZB23E32 SLP104 CHINO
 RWY36 \$=
 201906240417 SPECI KFTK 240417Z AUTO 18009KT 10SM -RA M 22/22 A2985 RMK
 A02 RAB17 SLP104 CHINO RWY36 \$=
 201906240356 METAR KFTK 240356Z AUTO 18009KT 10SM M 22/22 A2986 RMK A02
 RAB0259E24 SLP108 P0000 T02180218
 CHINO RWY36 \$=
 201906240324 SPECI KFTK 240324Z AUTO 19011KT 10SM M 22/22 A2986 RMK A02
 RAB0259E24 SLP108 CHINO RWY36 \$=
 201906240310 SPECI KFTK 240310Z AUTO 19008KT 10SM -RA M 22/22 A2986 RMK
 A02 LTG DSNT SE RAB0259 PRESRR SLP108
 CHINO RWY36 \$=
 201906240259 SPECI KFTK 240259Z AUTO 19008KT 10SM -RA M 22/22 A2984 RMK
 A02 RAB59 SLP101 CHINO RWY36 \$=
 201906240256 METAR KFTK 240256Z AUTO 19007KT 10SM M 22/22 A2984 RMK A02
 RAE23DZB23E25RAB26E36 SLP101 P0001
 60004 T02210216 CHINO RWY36 \$=
 201906240236 SPECI KFTK 240236Z AUTO 17009G19KT 10SM M 22/21 A2983 RMK
 A02 LTG DSNT S RAE23DZB23E25RAB26E36
 SLP098 CHINO RWY36 \$=
 201906240226 SPECI KFTK 240226Z AUTO 18012KT 10SM -RA M 22/21 A2983 RMK
 A02 LTG DSNT S RAE23DZB23E25RAB26
 SLP098 CHINO RWY36 \$=
 201906240225 SPECI KFTK 240225Z AUTO 18012KT 10SM M 22/21 A2984 RMK A02
 LTG DSNT S RAE23DZB23E25 SLP101 CHINO
 RWY36 \$=
 201906240217 SPECI KFTK 240217Z AUTO 18013KT 10SM -RA M 22/21 A2983 RMK
 A02 SLP098 CHINO RWY36 \$=
 201906240156 METAR KFTK 240156Z AUTO 19010KT 10SM -RA M 22/22 A2985 RMK
 A02 RAE05DZB05E06RAB15E42DZB42E47RAB47
 SLP105 P0000 T02220218 CHINO RWY36
 \$=
 201906240115 SPECI KFTK 240115Z AUTO 17012KT 10SM -RA VCTS M 23/22 A2984
 RMK A02 RAE05DZB05E06RAB15 SLP102
 CHINO RWY36 \$=
 201906240106 SPECI KFTK 240106Z AUTO 16015KT 10SM VCTS M 23/22 A2985 RMK
 A02 RAE05DZB05E06 SLP105 CHINO RWY36
 \$=
 201906240102 SPECI KFTK 240102Z AUTO 17014G30KT 8SM -RA VCTS M 23/22 A2985
 RMK A02 PRESFR SLP105 CHINO RWY36
 \$=
 201906240056 METAR KFTK 240056Z AUTO 17019G30KT 6SM -RA VCTS M 23/21 A2987
 RMK A02 PK WND 18030/52 RAB49 SLP112
 P0003 T02330210 CHINO RWY36 \$=
 201906240049 SPECI KFTK 240049Z AUTO 18010KT 10SM -RA M 24/20 A2987 RMK
 A02 LTG DSNT S RAB49 SLP112 CHINO
 RWY36 \$=

201906232356 METAR KFTK 232356Z AUTO 15006KT 10SM M 24/19 A2987 RMK A02
 SLP112 60000 T02370185 10302 20212
 57026 CHINO RWY36 \$=
 201906232308 SPECI KFTK 232308Z AUTO 12006KT 10SM M 23/19 A2988 RMK A02
 PRESFR SLP116 CHINO RWY36 \$=

 201906232256 METAR KFTK 232256Z AUTO 11006KT 10SM M 22/21 A2990 RMK A02 SLP123
 T02220213 CHINO RWY36 \$=

 201906232156 METAR KFTK 232156Z AUTO 10004KT 10SM M 21/21 A2991 RMK A02
 LTG DSNT SE RAE14DZB14E23 SLP127
 P0000 T02130213 CHINO RWY36 \$=

 201906232123 SPECI KFTK 232123Z AUTO 36004KT 10SM M 22/21 A2992 RMK A02
 LTG DSNT N-NE AND SE-S RAE14DZB14E23
 SLP130 CHINO RWY36 \$=
 201906232119 SPECI KFTK 232119Z AUTO 04006KT 10SM -DZ M 22/21 A2991 RMK
 A02 LTG DSNT N-NE AND SE-S RAE14DZB14
 SLP126 CHINO RWY36 \$=
 201906232057 SPECI KFTK 232057Z AUTO 22003KT 10SM -RA M 22/20 A2993 RMK
 A02 LTG DSNT N AND S-SW PRESFR SLP133
 CHINO RWY36 \$=
 201906232056 METAR KFTK 232056Z AUTO 24005KT 10SM -RA M 22/20 A2995 RMK
 A02 PK WND 25031/28 LTG DSNT S-SW
 RAB48 SLP140 P0000 60000 T02200199
 55013 CHINO RWY36 \$=
 201906232051 SPECI KFTK 232051Z AUTO 27008KT 10SM -RA M 22/19 A2996 RMK
 A02 LTG DSNT S-N RAB48 PRESRR SLP143
 CHINO RWY36 \$=
 201906232048 SPECI KFTK 232048Z AUTO 30010G26KT 10SM -RA M 23/19 A2994
 RMK A02 LTG DSNT S-N RAB48 SLP137
 CHINO RWY36 \$=
 201906232044 SPECI KFTK 232044Z AUTO 31010G26KT 10SM M 23/19 A2995 RMK
 A02 LTG DSNT S-N PRESFR SLP140 CHINO
 RWY36 \$=
 201906232036 SPECI KFTK 232036Z AUTO 28012G31KT 10SM M 26/20 A2997 RMK
 A02 WSHFT 27 LTG DSNT N AND S-W SLP146
 CHINO RWY36 \$=
 201906232032 SPECI KFTK 232032Z AUTO 28019G31KT 10SM M 28/22 A2997 RMK
 A02 LTG DSNT SW-N PRESRR SLP145 CHINO
 RWY36 \$=
 201906232027 SPECI KFTK 232027Z AUTO 24012G24KT 10SM M 29/23 A2995 RMK
 A02 LTG DSNT SW-NW SLP138 CHINO RWY36
 \$=
 201906231956 METAR KFTK 231956Z AUTO 16009KT 10SM M 30/23 A2993 RMK A02
 SLP131 T03010233 CHINO RWY36 \$=

201906231939 SPECI KFTK 231939Z AUTO 15010KT 10SM M 30/24 A2992 RMK A02
 SLP128 CHINO RWY36 \$=
 201906231909 SPECI KFTK 231909Z AUTO 17008KT 10SM M 30/24 A2994 RMK A02
 PRESFR SLP135 CHINO RWY36 \$=
 201906231856 METAR KFTK 231856Z 20007KT 10SM BKN030 BKN050 BKN200 30/24
 A2996 RMK SLP141 \$=
 201906231758 METAR KFTK 231758Z 19006KT 10SM BKN030 BKN200 29/23 A2998
 RMK SLP148 57012 \$=
 201906231659 METAR KFTK 231659Z 18010G16KT 10SM SCT030 SCT120 SCT250 28/22
 A3000 RMK SLP155 \$=
 201906231559 METAR KFTK 231559Z 19008KT 10SM FEW025 SCT120 SCT250 27/22
 A3000 RMK SLP155 \$=
 201906231456 METAR KFTK 231456Z 20008KT 10SM FEW010 BKN030 BKN250 26/23
 A3002 RMK SLP162 58002 \$=
 201906231358 METAR KFTK 231358Z 14005KT 10SM SCT010 SCT250 22/22 A3002
 RMK SLP163 \$=
 201906231344 SPECI KFTK 231344Z 13006KT 5SM BR BKN005 OVC010 21/21 A3002
 RMK \$=
 201906231257 METAR KFTK 231257Z 11005KT 1/2SM FG OVC001 20/20 A3003 RMK
 SLP167 \$=
 201906231155 METAR KFTK 231155Z 07004KT 1/2SM R18/3000V4000FT FG OVC001
 20/20 A3002 RMK SLP163 60000 70105
 50002 \$=
 201906231056 METAR KFTK 231056Z 11004KT 1/4SM R18/2400V2800FT FG OVC001
 19/19 A3003 RMK SLP167 \$=
 201906231026 SPECI KFTK 231026Z AUTO 11004KT 1 1/4SM BR M 19/19 A3003
 RMK A02 VIS 1 1/4V4 SLP167 CHINO
 RWY36 \$=
 201906230956 METAR KFTK 230956Z AUTO 07003KT 6SM BR M 19/19 A3002 RMK
 A02 SLP163 T01930193 CHINO RWY36
 \$=
 201906230856 METAR KFTK 230856Z AUTO 06004KT 10SM M 19/19 A3002 RMK A02
 SLP163 60000 T01940194 58009 CHINO
 RWY36 \$=
 201906230854 SPECI KFTK 230854Z AUTO 06004KT 10SM M 20/20 A3001 RMK A02
 SLP159 CHINO RWY36 \$=
 201906230756 METAR KFTK 230756Z AUTO 00000KT 10SM M 20/20 A3003 RMK A02
 SLP166 T01960196 CHINO RWY36 \$=
 201906230722 SPECI KFTK 230722Z AUTO 00000KT 10SM M 20/20 A3003 RMK A02
 SLP166 CHINO RWY36 \$=
 201906230656 METAR KFTK 230656Z AUTO 00000KT 10SM M 20/20 A3005 RMK A02
 RAB0557E06DZB06E09 SLP173 P0000 T01980198
 CHINO RWY36 \$=
 201906230557 SPECI KFTK 230557Z AUTO 00000KT 10SM -RA M 21/21 A3004 RMK
 A02 RAB57 SLP170 CHINO RWY36 \$=
 201906230556 METAR KFTK 230556Z AUTO 00000KT 10SM M 21/21 A3004 RMK A02
 DZE0458 SLP170 P0000 60000 T02050205
 10246 20201 50001 CHINO RWY36 \$=
 201906230458 SPECI KFTK 230458Z AUTO 04005KT 10SM M 21/21 A3005 RMK A02

DZE58 SLP173 CHINO RWY36 \$=
 201906230456 METAR KFTK 230456Z AUTO 05005KT 10SM -DZ M 21/21 A3006 RMK
 A02 DZB52 SLP177 P0000 T02080208
 402580175 CHINO RWY36 \$=
 201906230452 SPECI KFTK 230452Z AUTO 04003KT 10SM -DZ M 21/21 A3006 RMK
 A02 DZB52 SLP177 CHINO RWY36 \$=
 201906230419 SPECI KFTK 230419Z AUTO 00000KT 10SM M 21/21 A3007 RMK A02
 SLP180 CHINO RWY36 \$=
 201906230356 METAR KFTK 230356Z AUTO 03005KT 10SM M 21/21 A3005 RMK A02
 DZB43E53 SLP173 P0000 T02140214 CHINO
 RWY36 \$=
 201906230353 SPECI KFTK 230353Z AUTO 03005KT 10SM M 22/22 A3005 RMK A02
 DZB43E53 SLP173 CHINO RWY36 \$=
 201906230343 SPECI KFTK 230343Z AUTO 00000KT 10SM -DZ M 21/21 A3005 RMK
 A02 DZB43 SLP174 CHINO RWY36 \$=
 201906230256 METAR KFTK 230256Z 06004KT 10SM FEW030 22/22 A3004 RMK SLP171
 T02150215 51027 CHINO RWY36 \$=
 201906230156 METAR KFTK 230156Z 00000KT 10SM FEW030 22/21 A3004 RMK SLP171
 T02180214=
 201906230056 METAR KFTK 230056Z 09005KT 10SM FEW030 23/21 A2998 RMK SLP150
 T02340211=
 201906222356 METAR KFTK 222356Z 05007KT 10SM FEW030 FEW120 25/21 A2996
 RMK SLP143 T02460205 10258 20246
 57038=
 201906222256 METAR KFTK 222256Z 04005KT 10SM FEW030 SCT120 25/20 A2999
 RMK SLP153 T02520204=
 201906222156 METAR KFTK 222156Z 28004KT 10SM FEW030 BKN120 25/21 A3005
 RMK SLP173 T02490208=

No short TAF reports from KFTK in databse.

#####

large TAF from KFTK

#####

201906242044 TAF AMD KFTK 242044Z 2420/2523 25012KT 9999 BKN015 QNH2974INS
 BECMG 2423/2424 27012G18KT 9999 SCT015 BKN030
 QNH2982INS
 BECMG 2506/2507 VRB06KT 9999 SCT028 QNH2994INS
 TX26/2517Z TN19/2511Z=
 201906241753 TAF AMD KFTK 241753Z 2417/2523 15012KT 8000 -RA BKN005 OVC020
 QNH2974INS
 BECMG 2419/2420 27012KT 9000 -SHRA OVC007
 QNH2978INS
 TEMPO 2421/2424 27015G25KT -TSRA BKN007CB
 OVC020
 BECMG 2423/2424 27012G18KT 9999 NSW FEW015
 BKN030 QNH2982INS
 BECMG 2506/2507 VRB06KT 9999 SCT028 QNH2994INS
 TX26/2517Z TN19/2511Z=

201906241700 TAF KFTK 241700Z 2417/2523 15012KT 8000 -RA OVC020 QNH2974INS
 BECMG 2418/2419 27015G25KT 9000 -SHRA OVC020
 QNH2978INS
 TEMPO 2421/2424 -TSRA BKN015CB OVC020
 BECMG 2423/2424 27015G25KT 9999 NSW FEW015
 BKN030 510043 QNH2982INS
 BECMG 2506/2507 VRB06KT 9999 SCT028 QNH2994INS
 TX26/2517Z TN19/2511Z=

201906241135 TAF AMD KFTK 241135Z 2411/2515 24009KT 9999 SCT150 BKN200 QNH2979INS
 TEMPO 2412/2414 -TSRA SCT010 OVC020CB
 BECMG 2414/2415 25009KT 6000 -SHRA BKN020
 OVC150 QNH2976INS
 TEMPO 2417/2420 27015G20KT -TSRA SCT010 OVC020CB
 BECMG 2419/2420 26012KT 9999 NSW FEW075
 QNH2978INS
 BECMG 2509/2510 09006KT 9999 FEW090 QNH2993INS
 TX25/2421Z TN19/2509Z=

201906240905 TAF KFTK 240905Z 2409/2515 24009KT 9999 SCT150 BKN200 QNH2979INS
 BECMG 2414/2415 25009KT 6000 -SHRA BKN020
 OVC150 QNH2976INS
 TEMPO 2415/2419 27015G20KT -TSRA SCT010 OVC020CB
 BECMG 2418/2419 26012KT 9999 NSW FEW075
 QNH2978INS
 BECMG 2509/2510 09006KT 9999 FEW090 QNH2993INS
 TX25/2421Z TN19/2509Z=

201906240105 TAF KFTK 240105Z 2401/2507 19009KT 8000 -SHRA SCT020 BKN040 QNH2980INS
 TEMPO 2401/2402 20035G50KT 4800 -TSRAGR
 OVC020CB
 BECMG 2403/2404 21009KT 9999 NSW BKN040 QNH2977INS
 BECMG 2414/2415 24006KT 9999 -RA BKN030
 QNH2989INS
 BECMG 2419/2420 23006KT 9999 NSW SCT060 QNH2986INS
 BECMG 2504/2505 26006KT 9999 FEW070 QNH2990INS
 TX25/2421Z TN19/2414Z=

201906232250 TAF AMD KFTK 232250Z 2322/2423 17012KT 9000 -SHRA BKN020 OVC250
 QNH2993INS
 TEMPO 2322/2323 -TSRA OVC020CB
 BECMG 2323/2324 22009KT 9999 NSW SCT020 BKN040
 QNH2978INS
 TEMPO 2402/2405 -TSRA OVC020CB
 BECMG 2417/2418 24006KT 9999 -RA BKN030 QNH2980INS
 BECMG 2419/2420 23006KT 9999 NSW SCT060
 QNH2982INS
 TX30/2322Z TN21/2412Z=

201906231950 TAF AMD KFTK 231950Z 2319/2423 17012KT 4800 SHRA SCT020 SCT250
 QNH2993INS
 TEMPO 2320/2323 24050G60KT TSRA OVC020CB
 BECMG 2323/2324 22009KT 9999 NSW SCT020
 BKN040 QNH2978INS

BECMG 2417/2418 24006KT 9999 -RA BKN030 QNH2980INS
 BECMG 2419/2420 23006KT 9999 NSW SCT060
 QNH2982INS
 TX30/2320Z TN21/2412Z=
 201906231700 TAF KFTK 231700Z 2317/2423 17012KT 9999 SCT020 SCT250 QNH2993INS
 TEMPO 2320/2323 24020G25KT TSRA OVC020CB
 BECMG 2323/2324 22009KT 9999 SCT020 BKN040
 QNH2978INS
 BECMG 2417/2418 24006KT 9999 -RA BKN030 QNH2980INS
 BECMG 2419/2420 23006KT 9999 NSW SCT060
 QNH2982INS
 TX30/2320Z TN21/2412Z=
 201906231400 TAF AMD KFTK 231400Z 2314/2415 17009KT 9999 SCT010 SCT250 QNH2993INS
 TEMPO 2314/2320 24009KT -TSRA OVC050CB
 BECMG 2323/2324 22009KT 9999 SCT020 BKN040
 QNH2978INS
 TX30/2320Z TN21/2314Z=
 201906231142 TAF AMD KFTK 231142Z 2311/2415 26009KT 0500 FG BKN002 QNH2993INS
 TEMPO 2311/2314 26012G18KT 6000 -TSRA OVC050CB
 BECMG 2312/2314 25010G15KT 9999 NSW SCT020
 BKN050 QNH2985INS
 TEMPO 2317/2324 23015G20KT 8000 -TSRA OVC010CB
 BECMG 2323/2324 22009KT 9999 SCT020 BKN040
 QNH2978INS
 TX30/2320Z TN19/2311Z=
 201906231045 TAF AMD KFTK 231045Z 2310/2415 26009KT 1600 BR BKN005 QNH2993INS
 TEMPO 2310/2314 26012G18KT 6000 -TSRA OVC050CB
 BECMG 2312/2314 25010G15KT 9999 NSW SCT020
 BKN050 QNH2985INS
 TEMPO 2317/2324 23015G20KT 8000 -TSRA OVC010CB
 BECMG 2323/2324 22009KT 9999 SCT020 BKN040
 QNH2978INS
 TX30/2320Z TN20/2310Z=
 201906230900 TAF KFTK 230900Z 2309/2415 26009KT 9999 BKN050 QNH2993INS
 TEMPO 2309/2314 26012G18KT 6000 -TSRA OVC050CB
 BECMG 2312/2314 25010G15KT 9999 SCT020 BKN050
 QNH2985INS
 TEMPO 2317/2324 23015G20KT 8000 -TSRA OVC010CB
 BECMG 2323/2324 22009KT 9999 SCT020 BKN040
 QNH2978INS
 TX30/2320Z TN20/2309Z=
 201906230815 TAF AMD KFTK 230815Z 2308/2407 26009KT 9999 BKN050 QNH3000INS
 TEMPO 2309/2314 26012G18KT 6000 -TSRA OVC050CB
 BECMG 2313/2314 25010G15KT 9999 OVC005 QNH3000INS
 TEMPO 2317/2320 23015G20KT 8000 -TSRA OVC010CB
 BECMG 2319/2320 22009KT 9999 SCT020 BKN040
 QNH2989INS
 TX29/2320Z TN20/2311Z=
 201906230100 TAF KFTK 230100Z 2301/2407 33009KT 9999 FEW030 BKN120 QNH2997INS

BECMG 2305/2306 26006KT 9999 OVC005 QNH3002INS
BECMG 2312/2313 25010G15KT 9999 OVC005 QNH3000INS
TEMPO 2317/2320 23015G20KT 8000 -TSRA OVC010CB
BECMG 2319/2320 22009KT 9999 SCT020 BKN040
QNH2989INS
TX29/2320Z TN20/2311Z=