



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: August 5, 2019
Person Contacted: Will Dawson, Dawson Aircraft
NTSB Accident Number: CEN19LA194 – Ft. Smith, Arkansas

Narrative:

Mr. Dawson reported that about 15 gallons of fuel was drained from the left-wing fuel tank and less than 1/4 gallon was drained from the right fuel tank. The fuel tanks appeared to be intact and no fuel leakage was observed.

----- End of entries -----