

ENGINE DATA

MODEL NO. TPE331- 10- 511M SERIAL NO. P- 42076 G10-157 TOTAL ENGINE WEIGHT _____ LBS
TAKEOFF RATING _____ 940 HP@ _____ 1591 RPM (_____ 100 %)
MAXIMUM CONTINUOUS RATING _____ 900 HP@ _____ 1591 RPM (_____ 100 %)
OIL GRADE SEE FLIGHT MANUAL OIL PRESSURE SEE FLIGHT MANUAL MAXIMUM OIL TEMP SEE FLIGHT MANUAL
FUEL SEE FLIGHT MANUAL MAXIMUM TURBINE DISCHARGE TEMPERATURE (TDT) 1049 °F (565 °C)

PROPELLER DATA

MANUFACTURER _____
MODEL NUMBER _____ SERIAL NUMBER _____ 07/22/2019 08:35

OWNER DATA

ENGINE ☐
MODULE ☐
SERIAL NUMBER _____

DATE

SERVICE RECORD

DESCRIPTION OF INSPECTIONS, REPAIRS AND OVERHAULS
ENDORSE ALL INSPECTIONS AND REPAIRS WITH NAME, RATING AND CERTIFICATE NUMBER.

PAGE _____

N766BF
Ayres S2R G510
S/N G10-157

Garrett TPE331-10-511M S/N P-42076

Date: February 23, 2018

Hobbs Time: 349.0

Total Time 16602.6

TSCAM 349.0

TSHOT 349.0

Drained Oil. Serviced with BP2380 oil. Replaced Oil filter. Replaced fuel filter. Clean fuel finger strainer. Performed Igniters operational check found to be normal. Removed starter Generator Overhauled and reinstalled. Removed and inspected plenum drains. Lubricated control rod ends. Engine inspected and serviced I/A/W Garrett inspection guide.

I certify that this Powerplant has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

Patrick McCarty

A&P

07/22/2019 08:34

REPAIRS LISTED AND SIGNED OFF IS IN ACCORDANCE WITH THE MANUFACTURER'S INSPECTION INSTRUCTIONS

SERIAL NUMBER

SERVICE RECORD

DESCRIPTION OF INSPECTIONS, REPAIRS AND OVERHAULS
ENDORSE ALL INSPECTIONS AND REPAIRS

ENDORSE ALL INSPECTIONS AND REPAIRS WITH NAME, RATING AND CERTIFICATE NUMBER

PAGE

DESCRIPTION OF INSPECTIONS, REPAIRS AND OVERHAULS ENDORSE ALL INSPECTIONS AND REPAIRS WITH NAME, RATING AND CERTIFICATE NUMBER.							
DATE	HOURS THIS FLIGHT	CYCLES THIS FLIGHT	ACCUMULATIVE TOTALS				DESCRIPTION OF WORK PERFORMED
			HOURS		CYCLES		
			SINCE NEW	SINCE O/H	SINCE NEW	SINCE O/H	

Garrett TPE331-10-511M S/N P-42076

Date: April 20, 2018

Hobbs Time; 354.6

Total Time 16608.2

TSCAM 354.6

TSHOT 354.6

Removed high pressure bleed air fitting that was installed I/A/W Ayres Drawing 19871 and installed plate. C/W AD 2018-02-14 by inspection of combustion chamber I/A/W Honeywell Service Bulletin TPE331-72-2178, Revision 0, dated May 3, 2011. Due again at hobbs 804.6 HRA

Patrick McCarty

A&P

DATE	5/2/2018	HODDS	396.0		OILW AD 2018-13-05-	I/A/W PAR.G1-3 BY	
					OBTAINING AN OIL FILTER SAMPLE THAT WAS		
					SUBMITTED FOR ANALYSIS AT AWT ISO/IEC 17025 LAB.	TPE331	
					NEXT DUE AT 546.0	631043	
					Joshua Baker ATP	[REDACTED]	[REDACTED]

07/22/2019 08:34

TOTALS TO DATE

ENGINE ☐
MODULE ☐
SERIAL NUMBER _____

SERVICE RECORD

DESCRIPTION OF INSPECTIONS, REPAIRS AND OVERHAULS
ENDORSE ALL INSPECTIONS AND REPAIRS WITH NAME, RATING AND CERTIFICATE NUMBER.

PAGE _____

DATE

Date; February 2, 2019

Hobbs Time; 507.5 Total Time 16761.1 TSHOT 507.5 TSCAM 507.5

Drained Oil. Replaced Oil filter. Replaced fuel filter. Clean fuel finger strainer. Performed Igniters operational check found to be normal. Removed starter Generator Overhauled and reinstalled. Removed and inspected plenum drains. Lubricated control rod ends. Engine inspected and serviced I/A/W Garrett inspection guide. Removed fuel nozzles overhauled and reinstalled. Removed fuel control C/W AD2016-21-07 Par 2 Group 5, by inspection and spline measurement I/A/W TPE331-10 Report 72-00-27 due again at 1507.5 C/W AD 2018-17-15 by inspection of the combustion section in accordance with Honeywell Service Bulletin (SB) TPE331-72-2178, Revision 0, dated May 3, 2011, or SB TPE331-72-2179, Revision 0, dated May 3, 2011, Due again at 957.5

AD 2018-13-05 by oil analysis and oil filter analysis for wear metals and evaluate filter contents using paragraphs 1.D.(4) and (5) of Honeywell SIL P331-97, Revision 11, dated July 23, 2008. Guidelines for interpreting analysis results can be found in paragraph (8) of Honeywell SIL P331-97 Due again at 657.5 Serviced with BP2380 oil. Test ran after inspection

I certify that this Powerplant has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

Patrick McCarty

A&P [REDACTED] A

07/22/2019 08:34

THIS CERTIFIES THAT THE TYPE OF INSPECTION LISTED AND SIGNED OFF IS IN ACCORDANCE WITH THE MANUFACTURER'S INSPECTION INSTRUCTIONS
AS DEFINED IN CURRENT APPLICABLE MAINTENANCE MANUAL.

PX-3107-51 BACK

ENGINE ☐

SERVICE RECORD

PAGE _____

NE ☐
LE ☐

L NUMBER _____

SERVICE RECORD

PAGE _____

DESCRIPTION OF INSPECTIONS, REPAIRS AND OVERHAULS

ENDORSE ALL INSPECTIONS AND REPAIRS WITH NAME, RATING AND CERTIFICATE NUMBER.

Date; July 19, 2019

Hobbs Time; 603.9

Total Time 16857.5

TSHOT 603.9 TSCAM 603.9

Replaced Oil filter. Replaced fuel filter. Clean fuel finger strainer. Performed Igniters operational check found to be normal. Removed and inspected plenum drains. Lubricated control rod ends. Engine inspected and serviced I/A/W Garrett inspection guide. AD 2018-13-05 by oil analysis and oil filter analysis for wear metals and evaluate filter contents using paragraphs 1.D.(4) and (5) of Honeywell SIL P331-97, Revision 11, dated July 23, 2008. Guidelines for interpreting analysis results can be found in paragraph (8) of Honeywell SIL P331-97 Due again at 753.9 Serviced with BP2380 oil. Test ran after inspection

I certify that this Powerplant has been inspected in accordance with an 100 Hour inspection and was determined to be in an airworthy condition.

Patrick McCarty

A&P [REDACTED] IA

07/22/2019 08:33

Garrett TPE331-10-511M S/N P-42076C	Reference N766BF	Last completed Date Time	Next Due Date Time	Time Remaining 7/19/2019	Inspection Interval	Time since
603.9		Aircraft Total Time				
A/C S/N G10-157		5085.4				
Garrett 100 Hr. SOAP and filter LEFT 33	SB331-72-0180	603.9	753.9	150		150
Garrett 100 Hr. Corrosion Insp.	SB331-72-0180	507.5	957.5	353.6		450 96.4
Fuel Nozzle Clean/Insp.	SB331-72-0180	507.5	957.5	353.6		450 96.4
Fuel Pump/ FCU mating spline	AD 2016-21-07	507.5	1507.5	903.6		1000 96.4
Hot Section Overhaul	SB331-72-0180	0	2500	1896.1		2500 603.9
Engine Opverhaul CAM	SB331-72-0180	0	5000	4396.1		5000 603.9
Starter/generator Overhaul	SB331-72-0180	0	1000	396.1		1000 603.9
Propeller overhaul S/N CDAS072MI	SB137AB	507.5	5507.5	4903.6		5000 96.4
Propeller govenor overhaul	SB331-72-0180	0	5000	4396.1		5000 603.9
Propeller Dyn. Balance	SIL P331-52R7	0	1000	396.1		1000 603.9
Gearbox Inspection	SB331-72-0180	0	5000	4396.1		5000 603.9
Engine Total time		16857.5	tshot	603.9		
Transponder Inspection	FAR 91.413					
Torque Sensor		0				
fuel heater		0				
Engine Cycles	Landings	96	Total Cycles	127		
Takeoffs/Landing	625		Starts/Shutdowns	31		
Part Disc	1st Stage	2nd Stage	3rd Stage	Seal Plate		
Part Number	310864-2	3102106-10	3102655-2	3102484-1		
Serial Number	6-03229-3734	980134509321	3-01345-5122	6-03501-7363		
Date Installed	10/13/2003	12/20/1998	12/20/1998	12/20/1998		
Date Operation	2/2/2016	2/2/2016	2/2/2016	2/2/2016		
Total Equavelant Cycles	2937.166667	7030.166667	4953.166667	10299.16667		
Life limit	20000	15000	6000	20000		
Cycles remaining I/A/W AD06-14-03	17062.83333	7969.833333	1046.833333	9700.833333		
Total Cycles this date 07/19/19	3064.166667	7157.166667	5080.166667	10426.16667		

07/22/2019 08:3