

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number
19				

**Ayres Thrush 510 S/N 157
N766BF**

Date; February 2 , 2019
Hobbs Time 507.5 Total Time 4989.0

Serviced Wheel bearings, brakes, fuel filter, Removed serviced batteries, and all flight control systems. Lubricated all fittings and hinges. Inspected aircraft I/A/W manufactures Ayres Thrush inspection guide. Removed Starter generator and reinstalled after overhaul and spline lubercation. All continued airworthiness Inspection requirements completed. Replaced tail wheel Bolts NAS646-6-36. Replaced tail wheel tire, tube. Replaced control stick bolt I/A/W SB AG-27A . Replaced tail wheel Bolts NAS646-6-36, AN7-54A. Replaced Seat covers with new WS1021-12-00 and WS1021-29-00. Replaced Tach generator with overhauled 32005-030. Replaced tail wheel Bolts NAS646-6-36, AN7-54A. I/A/W Thrush maintenance Manual . AD search time 03 2019

[Redacted Signature]

I certify that this aircraft has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

[Redacted Signature]
Patrick McCarty
A&P [Redacted] A

07/22/2019 08:40



Ayres Thrush 510 S/N 157
N766BF

Date: July 19, 2019
Hobbs Time 603.9

Total Time 5085.4

Serviced Wheel bearings, brakes, fuel filter, Removed serviced batteries, and all flight control systems. Lubricated all grease fittings and hinges. Inspected aircraft I/A/W manufactures Ayres Thrush inspection guide. All continued airworthiness Inspection requirements completed Replaced oil cooler with overhauled 17072C . AD search thru 2019-14

I certify that this aircraft has been inspected in accordance with an 100 Hour inspection and was determined to be in an airworthy condition.


Patrick McCarty
A&P  IA

07/22/2019 08:40