

 DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION REPORT OF AIRCRAFT ACCIDENT (Continuation Sheet)	REPORT DATE November 04, 2019	REPORT NO. 19-001-BCT-FCT
	NAME OF REPORTING FACILITY Boca Raton FCT (BCT)	

14. CHRONOLOGICAL SUMMARY OF FLIGHT
September 11, 2019

ALL TIMES BELOW ARE COORDINATED UNIVERSAL TIME
UNLESS OTHERWISE SPECIFIED


1421 N2890T called Ground Control (GC) for taxi instructions to remain in the pattern for touch and goes. GC instructed N2890T to taxi to Runway 05 and hold short of Taxiway Papa 9.

1426 GC instructed N2890T to enter Runway 05 at Taxiway Foxtrot and back taxi to exit the runway at Taxiway Golf to continue on Taxiway Papa for a full length departure from Runway 05. N2890T acknowledged the instructions and proceeded onto Runway 05 exiting at Taxiway Golf.

1430 N2890T requested takeoff clearance full length Runway 05. Local Control (LC) cleared N2890T for takeoff Runway 05 without delay.

1433 N2890T reported he was coming back. LC asked N2890T to repeat his transmission. N2890T responded he was coming back in. LC asked N2890T if he was going to need Runway 23 again. N2890T did not respond. LC instructed N2890T to remain on the downwind, at which time N2890T was observed rapidly descending behind a hangar in the Northwest corner of the airport.

No More Follows



19-001-BCT-FCT
 N2890T

This Diagram Not To Scale