

Communication Summary

June 15, 2020

Information from: Nancy McAtee, NTSB Chemist



Summary & Factual Information: An examination of the engine from N578SP was conducted. An NTSB Chemist arranged for the oil sample, taken from the oil filter during that examination, to be sent to a laboratory for testing. The sample size limited possible testing. The results of the tests conducted, using American Society for Testing and Materials methods, revealed the sample's viscosity met the specifications of the required oil.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator