



Photo 1 – View of damage to the empennage (Courtesy of FAA)




Photo 2 – View of damage to the elevator and horizontal stabilizer (Courtesy of FAA)