

Communication Summary

July 30, 2020

Information from: Bryan Gammill, Pilot



Summary & Factual Information: The pilot of N570WH, B Gammill, was asked if there were any mechanical malfunctions with the helicopter. He, in part, reported:

There was no mechanical malfunction.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator