



The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
Maintenance Record
Information
CEN20FA010
Aberdeen South Dakota

Maintenance logbooks for the airframe and engine were not found. The only records that were available were work orders that were generated by Aberdeen Flying Service FBO, while assessing the airplane for an annual inspection on October 1, 2019. The inspection was not performed at the pilot's request. After the assessment was made, The FBO issued an Aircraft Condition Notice FAA Form 8620-1 and tagged the airplane. The notice stated, "Aircraft deemed un-airworthy due to numerous un-airworthy findings to include broken or cracked landing gear saddles. Other items as described on work order 1083 at ABR Flying Service".

DEPARTMENT OF TRANSPORTATION
UNITED STATES OF AMERICA

ATTENTION

DEPARTMENT OF TRANSPORTATION
UNITED STATES OF AMERICA

U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
AIRCRAFT CONDITION NOTICE
(See Privacy Act Statement on Reverse)

Date: October 3, 2019
Place of inspection: Aberdeen, SD

Registration number: N6483B
Serial number: 29683
Make: Cessna
Model: 172

NOTE: 1. The items listed below (☐ are) (☐ are not) considered to be an imminent hazard to safety. 2. Operation of the aircraft prior to correction (☐ will) (☐ will not) be contrary to pertinent Federal Aviation Regulations. 3. A Special Flight Permit (☐ will) (☐ will not) be required to be issued prior to operation if corrective action has not been taken. 4. A Special Flight Permit may be obtained from the office named below.

Aircraft deemed un-airworthy due to numerous un-airworthy findings to include broken or cracked landing gear saddles. Other items as described on work order 1083 at ABR Flying Service. END

The owner/lessee copy of this form was ☒ mailed ☐ delivered.

Inspector (Signature): [Redacted]
Dwight E. Flade
Office address: RAMP, ESDO, CL-27
District: CL

FAA Form 8620-1 (9-77) FORMERLY FAA FORM 8320-1

U.S. GOVERNMENT PRINTING OFFICE: 2013-545-800

PRIVACY ACT: Information on this form is requested under 49 U.S.C. 3201(a)(2)(A) and is not to be released to the public. The release of this information is prohibited by 49 U.S.C. 3201(a)(2)(A) and 49 U.S.C. 3201(a)(2)(B). The release of this information is prohibited by 49 U.S.C. 3201(a)(2)(A) and 49 U.S.C. 3201(a)(2)(B).

Alexander Lemishko

Senior Air Safety Investigator
NTSB Central Region Aviation