

Fox Todd

From: James Mullen <[REDACTED]>
Sent: Saturday, February 1, 2020 11:18 AM
To: Fox Todd
Subject: N6071R

Follow Up Flag: Follow up
Flag Status: Flagged

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Todd Fox NTSB , Time line of N6071R these are just estimated dates . Frank Edwards made the deal to purchase N6071R in August of 2019 . They purchased the airplane and trained with Jerry Sharpe . Frank said the HSI was not working correctly I contacted the last owner and said we should take care of this . He agreed we found an overhauled unit at Aerospace Components and Instruments LLC [REDACTED] Siloam Springs AR 72761 . Had it dropped shipped to Frank Edwards some time in late August . I think he had it installed and never heard any more squawks .

Frank Edwards dropped the airplane off on November 29th said he hit some birds on the left Prop . We removed the prop and sent it to Aero Propeller of Miami for inspection . They overhauled the prop and we reinstalled the prop . Also lubricated stuck waste gates , Installed overhauled pressure pump on the left engine and replaced outlet hose . I test flew the airplane on Saturday January 25th all systems were working properly the test flight was about 20 minutes . Frank Edwards picked up the airplane on Monday January 27th and I think he went back to KSRQ

Thanks Jimmy Mullen
Mullens Aviation