

National Transportation Safety Board

Office of Aviation Safety

Denver, CO 80239



CEN20FA070

AUTOPSY REPORT SUMMARY

ACCIDENT

Location: Springfield, Illinois
Date: January 28, 2020
Time: 1503 central standard time
Airplane: Piper PA-60-601P, Registration No. N6071R

AUTOPSY REPORT SUMMARY

An autopsy of the pilot was performed by Sangamon County Coroner's Office, Springfield, Illinois. The autopsy report was reviewed by the NTSB Investigator-In-Charge and Chief Medical Officer. According to the autopsy report, the cause of death was blunt force injuries, and the manner of death was accident. There was no evidence of inhalation of smoke or soot, or evidence of carbon monoxide inhalation within blood or tissues tested. The autopsy's toxicology results indicated the presence of caffeine in blood.