


N1011M


Fuel Selector Valve Visual – Valve was in the “Main” position when IIC arrived on scene. Signs of leaking prevalent inside the cabin upon removal of interior components, and in nose gear well as depicted in the following images.






2020/02/11





2020/02/11





2020/02/11