



MEMORANDUM

John M. Brannen II
Senior Air Safety Investigator
Central Region

Date: January 7, 2022
NTSB Accident Number: CEN20LA136 – Audubon, Iowa

Narrative:

An autopsy of the pilot was performed at the Iowa State Medical Examiner's facility in Ankeny, Iowa, under authority of the Audubon County Medical Examiner. The pilot's cause of death was multiple fractures and internal injuries sustained in the accident.

-----end of entries-----