



MEMORANDUM FOR RECORD

Shaun Williams
Senior Aviation Accident Investigator
Central Region

Date: 7/28/2020
NTSB Accident NumberCEN20LA145

Propeller Governor Exam

On July 27, 2020 the propeller governor was examined by the NTSB investigator-in-charge. Upon initial inspection, a small amount of foreign debris was found on the oil screen, but it was not completely blocking the flow of oil, as shown in figure 1.



Figure 1: Propeller governor oil screen

All components of the governor moved freely without any binding or rubbing noticed. Once the governor was disassembled, all oil paths and channels were found to be free of any debris and all contained residual oil. All gear splines were free of damage and the overall condition of the governor was unremarkable.

No anomalies were noted that would have precluded normal operation.

End of Record