



MEMORANDUM FOR RECORD

Michael J. Folkerts
Aviation Accident Investigator
Central Region

Date: 5/13/2021
NTSB Accident Number: CEN20LA248

An autopsy of the pilot was performed by Forensic Management Services of Texas in Beaumont, Texas. The cause of death was blunt force injuries.