

HARTZELL PROPELLER INC.
One Propeller Place
Piqua, Ohio 45356-2634 U.S.A.
Telephone: 937.778.4200
Telex: 4332032
Fax: 937.778.4391

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL _____

PROPELLER S/N _____

LOGBOOK # _____

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position Only

Propeller Model HC-G3YR-1RF

Propeller S/N ~~DY5364B~~ DY2636A

Blade Design F7282

Blade S/N's

No. 1 ~~173673~~ N53979

No. 2 ~~173662~~ K16453

No. 3 ~~173658~~ K16457

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather 30°

Start Lock _____

Low 12.5°

Reverse _____

Aircraft Manufacturer Piper

Aircraft Model PA-28R-200

S/N 7335047

Registration N15302

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
5/1/02	0	0	4938.76	Installed this new prop on IO-360-C1C
			Tach 2463.89	S/N L-9719-5A which is installed on PA28R-200
				N15302 S/N 7335047 under STC #4528NM
				see 337 this date for details
1/26/07	2394.63	0	Tach 4958.52	Installed prop after OVH at CRS#R5DR343X on W/O #10354
9/26/07	2697.68	165.5	Tach 138.0	New Tach
5/8/08	2772.88	376.35	Maint. hrs 0	Maint. hrs installed
4/20/12	4641.98	2247.35	1871.0	Installed prop after OVH at CRS#R5DR343X on W/O #13578
11/10/16	6623.18	1981.2	Maint. hrs 2852.2	Installed prop after OVH at CRS#7RDR559C on W/O #1507
4/14/17	6802.68	179.5	Maint. hrs 4036.7	
8/3/17	7146.18	342.5	Maint. hrs 4195.7	Installed prop after OVH at CRS#7RDR559C on W/O #16891, during this OVH the hub was replaced with S/N DY2636A, blades S/N H53879, K16453, K16457 were installed CRS#UZGR810K W/O #0570

Propeller S/N: DY2636A has been overhauled on this date: 8/3/2017 I/A/W/ manual(s):

113B, 133C, 202A

Under W/O #: 16891. The Mechanic making THE INSTALLATION MUST C/W 14 cfr Part 43.9.

Texas Aircraft Propeller & Accessories
1711 County Road 130, Pearland TX 77581

FAA CRS# 7RDR559C

Signed: _____

Jordan Propeller Service, Inc.
CRS # EK2R797K

Dynamic balance propeller on:

AC N15302
with Chadwick 192A S/N 1507

Starting IPS 4

Ending IPS 07

Melvin A. Chance

(Approved for return to service)

2-5-2018

Date

Propeller S/N DY5369B has been overhauled
this date 1-10-07 I/A/W manual(s)

113B Rev 29; 133C Rev 19; 202A vol1
rev30; vol2rev28; vol3rev28; vol6rev28;

vol7rev29; vol8rev28; vol9rev28; vol10

rev28; vol11rev29

under W/O # 9626. The mechanic making
the installation must c/w 14 CFR Part 43.9.

R & D Propeller Service, Inc.

2528 Hatfield Rd., Pearland, TX 77581

FAA CRS# R5DR343X

Signed [REDACTED]
4958.52 tach

Prop new 5/17/02 Tach 2563.89

Prop OVH 1/26/07 Tach 4958.52 Total 2394.63

Propeller S/N DY5369B

has been repaired this date 9-26-07

I/A/W manual(s) 113B; 133C; 202A

under W/O # 10354. The mechanic
making the installation must c/w

14 CFR Part 43.9.

R & D Propeller Service, Inc.

2528 Hatfield Road, Pearland, Texas 77581

CRS# R5DR343X

SIGNED [REDACTED] 138.0
tach

165.05 SMOH

~~2559.68 TSN~~ time @ Tach R+R

2697.68 TSN

5/8/08

Installed a maintenance hm@ 349.3 tach

376.35 SMOH

2770.98 TSN

4/20/12 maintenance hrm, 101110
2247.35 SMOH
4641.98 TSN

Propeller S/N DY5369B has been overhauled
this date 4-20-12 I/A/W manual(s)
113B; 133C; 202A

under W/O # 13578 The mechanic making
the installation must c/w 14 CFR Part 43.9.
R & D Propeller Service, Inc.
2528 Hatfield Rd., Pearland, TX 77581
FAA CRS# R5DR343X
Signed [REDACTED]

11/10/16 maintenance hrm, 3852.2
1981.2 SMOH
6623.18 TSN

Propeller S/N: DY5369B has been overhauled on
this date: 11/9/2016 I/A/W/ manual(s):

113B, 133C, 202A

Under W/O #: 16468. The Mechanic making
THE INSTALLATION MUST C/W 14 cfr Part 43.9.

R&D Propeller Service, LLC.
2528 Hatfield Rd, Pearland TX 77581

FAA CRS# 7RDR559C

Signed: [REDACTED]

ANSON AVIATION

Make: Piper	Model: PA_28R_200	Reg. No.: N15302
Date: 11/10/16	S/N: 28R7335047	Tach Time: 3852.20
Propeller Log	Type: HC-C3YR-1RF	S/N: DY5369B
	Total Time: 6623.18	SOH: 0.0

Installed propeller HC-C3YR-1RF s/n DY5369B from CRS#7RDR559C
on W/O#16468 on PA-28R-200 s/n 735047. Torqued and tracked prop.
Prop checks normal during ground run.

This propeller was repaired and inspected in accordance with the current
Code of Federal Regulation and is approved for return to service with
respect to work performed. Pertinent details of this repair are on file at
CRS#UZGR810K under W/O#0275.

Authorized Signature: Dave Bray [REDACTED]

ANSON AVIATION

Make: Piper	Model: PA_28R_200	Reg. No.: N1530
Date: 01/05/19	S/N: 28R7335047	Tach Time: 117.4
Propeller Log	Type: HC-C3YR-1RF	S/N: DY5369B

I certify that this propeller has been inspected in accordance with a 100
hour inspection and was found to be in an airworthy condition. This
propeller was repaired and inspected in accordance with the current
Code of Federal Regulation and is approved for return to service with
respect to work performed. Pertinent details of this repair are on file at
CRS#UZGR810K under W/O#0954.

Authorized Signature: [REDACTED]

11/10/16 3852.2 Tach OVH 6623.18 Total
4/14/17 4031.7 Tach Repair W/O 16697 5802.68 Total