



Photo of airplane provided by FAA



Photo of the right side of the airplane where the side panel liberated, provided by FAA



Photo of liberated panel provided by FAA



Photo of rusted flight control surface with duct tape provided by FAA