



MEMORANDUM FOR RECORD

Aaron Sauer
Sr. Air Safety Investigator
Central Region

Date: 06/01/21
NTSB Accident Number: CEN20LA367

An autopsy of the pilot was performed for the Lawrence County, Illinois Coroner's Office, which listed the cause of death as impact trauma with fire due to airplane crash. The manner of death is accident.