



ALPHA AVIATION
MISSION OUTREACH CENTER, INC.



ALPHA AVIATION
MISSION OUTREACH CENTER, INC.



06/02/2020	N733CD	Model	S/N		Hour	TT	
Aircraft	Cirrus	SR-22	22-0134		2053.8	2053.8	
1. Inspect and service aircraft in accordance with an ANNUAL INSPECTION per FAR 43 Appendix D. 2. Clean lower cowl and replace missing aluminum tape where needed. 3. Reverse main tires on wheels for wear. 4. Reattach left main strut fairing fastener with Locktite 330. Inflate main tires to 62 PSI. 5. Run up complete, all systems normal, no leaks. Work performed in accordance with appropriate service publications by Randy Baumann. <i>This AIRCRAFT has been inspected in accordance with an ANNUAL INSPECTION and was found to be in airworthy condition.</i> Signature: _____ J R Baumann AP [REDACTED]							

N733CD Airframe Cirrus SR22 SN 0134



Alpha Aviation Mission Outreach Center Inc.

Muskogee, OK 74403

08/27/2020	N733CD	Model	S/N		Hour	TT	
Aircraft	Cirrus	SR-22	22-0134		2070.6	2070.6	
1. Install Garmin GDL-82 ADS-B out TSO'd unit, PN-010-01560-31, SN-4PF008453, IAW Garmin installation instruction manual 190-01810-00 Rev 5. Attached unit to pilot side kick panel using #8 screws. 2. Installed Garmin GA-35 GPS antenna, PN-013-00235-00, SN-191787 under glare shield IAW Garmin installation instruction manual 190-01810-00 Rev 5. Installed RG400 coax from ADS-B unit to antenna. 3. Unit configured by ABS Avionics using Garmin config tool. 4. Operational check ok. Signature: _____ J R Baumann AP							

NOTES:

NEXT DUE	DUE DATE	DUE TIME
----------	----------	----------

ANNUAL	6-2021	
--------	--------	--

ELT TEST	6-21	
----------	------	--

ELT BATTERY	03-23	
-------------	-------	--

ALTIMETER	5-22	
-----------	------	--

TRANSPONDER	5-22	
-------------	------	--

STATIC SYSTEM	5-22	
---------------	------	--

CAPS	12-21	
------	-------	--

LINE CUTTERS	04-23	
--------------	-------	--

MAGNETO 500 HR

2030.3 TTIS / SNEW ENGINE



ALPHA AVIATION
MISSION OUTREACH CENTER, INC.

Muskogee, OK 74403

1. Both mags re-installed after 500 hr inspection & repair by Aircraft Accessories of OK . Left mag PN BL-500556-1. SN D03DA080R. Right mag PN BL-500556-1, SN D15JA265R.
2. Clean, inspect, gap and reinstall spark plugs.
3. Replaced Scat hose from baffle to heat muff.
4. Changed oil and filter. Drained oil through screen and inspected filter – observed minimal contaminants. Installed new AA48108-2 filter and serviced w/ 7 qts Phillips XC20W50.

Signature: _____ **J R Baumann AP**



Muskogee, OK 74403

1. Reinstalled engine driven fuel pump after repair by Aircraft Accessories of OK.
2. Set up fuel system in accordance with Continental Motors Publication M-O, Rev. 1 dated Sep. 2019.
3. Run-up complete.

Signature: _____ J R Baumann AP



Muskogee, OK 74403

1. Inspect and service engine in accordance with an ANNUAL INSPECTION per FAR 43 Appendix D.
2. Compression's 48, 73, 72, 70, 55, 45/80. Std 44.
3. Clean, gap, inspect and re-install spark plugs with new copper gaskets.
4. Drain engine oil, remove and inspect filter – no metal found.
5. Installed new AA48108-2 filter and serviced w/ 7 qts Phillips XC20W50 & 1 Pint CamGuard.
6. Clean cowl and replace missing aluminum tape heat shielding where needed
7. Run up complete, all systems normal, no leaks. Mag drops 50/50. Lean rise 25.

Signature: _____ J R Baumann



ALPHA AVIATION
MISSION OUTREACH CENTER, INC.

06/02/2020	N733CD	Model	S/N	Hour	TT	TPOH
Aircraft	Cirrus	SR-22	22-0134	2053.8	2053.8	
Propeller	Hartzell	PHC-J3YF-1RF	FP7019B	2053.8	2053.8	1064.8
1. Inspect and service prop with ASG #5 in accordance with an ANNUAL INSPECTION per FAR 43 Appendix D. Signature: _____ J R Baumann AP [REDACTED]						