



HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

08/03/2018 Tach. Time 5005.72 Total Since Overhaul 1393.17
Hartzell HC-C3YR-1RF

INSPECTED AND LUBED PROPELLER IN ACCORDANCE WITH HARTZELL
SERVICE MANUAL AND AT THIS TIME AND DATE FOUND TO BE IN AN
AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE.

 A/P  I/A
Donald J. Shorney A/P  I/A

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

☐ **HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul

5-07-2020 Tach 5013.29 SPOH 1400.48

Inspect and service IAW an annual inspection and at this time and date deemed airworthy and is approved for return to service. -----

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul

Donald R. Imhof AS&P [REDACTED] IA

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul

Mech. Cert. # or Repair Station # _____