


AIRCRAFT LOG

Date	Aircraft Time	Recorder	Maintenance
08/03/2018	Tach. Time 5005.72	Air frame Total time 6735.98	
N57607 Piper PA36-285 s/n 36-7660006			
Removed all inspection covers and fairings. Checked flight control, cables, and pivot points. Checked and lubed all hinges and pullies. Inspected all nav. Lights, landing light and electrical wiring. Checked interior lights and instruments for security and operation. Inspected fuel lines and shut-off valves for operation and leaks. Installed two (2) new fuel tank drain valve p/n CCA-4350. Checked main landing gear, brakes, wheels and bearings. Installed new o-rings in brake calipers and serviced with hyd. 5606. Removed cleaned and inspected airframe fuel gascolator. Completed A/D 77-21-03 Rudder Spare inspection next due at annual. INSPECTED AIRFRAME IN ACCORDANCE WITH AN ANNUAL INSPECTION USING PIPER SERVICE MANUAL CHECK LIST AND AT THIS TIME AND DATE FOUND TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE.			
 Donald J. Shorney <i>A/P</i>		 <i>A</i>	
Total To Carry Forward			

3/10/2018 Tach. Tir
N57607 Piper PA36-

installed new Voltage
Aircraft is approved for

Donald J. Shorney

09/28/20

N57607 Piper

Replace Airsp

S/N 1145 ops ch



8/10/2018 Tach. Time 5005.72
N57607 Piper PA36-285 s/n 36-766006

No.

Installed new Voltage regulator p/n VSF7403A. S/n 80Q89901. Run-up and Ops checked OK.
Aircraft is approved for return to service.

[REDACTED] A/P [REDACTED] I/A
Donald J. Shorney A/P [REDACTED] I/A

09/28/2018 Tach Time 5005.72
N57607 Piper PA36-285 s/n 36-766006
Replace Airspeed Indicator with overhauled unit P/N 5-1470N4
s/n 1145 ops checked OK. approved for return to Service.

[REDACTED] A-P [REDACTED] I A

CRAFT LOG

Date	Aircraft Time	Recorder
------	---------------	----------

03/10/2019 Tach. Time 5007.72 Total Air- Frame Time 6737.98

Pawnee Brave

Piper PA36-285 s/n 36-7660006 N57607

Installed new airframe battery Gill part number G242 serial number G03020346. All work done in accordance with Teledyne Battery Instructions numbered TBP 1560 Rev 1 dated 03/01/17. Also Recommended Practices and care of battery number TBP DWG. No. 1555 Rev. 1. Aircraft run-up and tests OK. Aircraft is approved for return to service.

Donald J. Shorney A/P I/A


Total To Carry Forward				

Registration No. _____

5-07-2020 Tach 5013.29 TTAF 6743.29

Remove fairings and inspection covers. Inspect flight surfaces and controls. Lube hinges, pulleys and rod ends. Inspect electrical wiring and lights. Clean gascolator and inspect fuel lines. Check landing gear, tires and brakes. Repack wheel bearings For AD compliance see aircraft records. -----

This airframe has been inspected IAW an annual inspection and at this time and date deemed airworthy and is approved for return to service. -----

 Donald R. Imhof A&P  IA

5-07-2020 Tach 5013.29 TSMOH 1778.98

6. All work done in
ed 03/01/17. Also
1. Aircraft run-up and

Brandon, MS 39017
Service on Your Location
www.jimjeffriesairworks.com
24 Hr 980-507-9981

Signature