




The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
Witness Statement Summary
CEN20LA383
Henderson Texas
September 5 2020

A witness reported the following information:

- A witness, who was inside the FBO at RFI observed the airplane while it was landing and saw it taxi to the ramp to refuel.
- He later saw the airplane taxi for takeoff on runway 35.
- He observed the airplane takeoff from runway 35 and climb to about 150 feet. He thought that the engine appeared to lose power, but was still running. The airplane made a turn to the left after takeoff and appeared to stall. The airplane then disappeared behind a tree line.

Alexander Lemishko



Senior Air Safety Investigator
NTSB Central Region Aviation