

Log for Ultra Light Re-build.

JAN 2013 New Sails complete.

New Trike & Airframe's & Control's

New tires + Brakes

Motor Serial No 3984516

Hours? About 40 on the Engine?

Gear Box Was 2.0 to 1 Marked 2.58 to 1

Change Gears to 2.58 to 1 JAN 20-2013

New Prop 66x34 Put on Jan 2013

Again Re built Engine August 2019

Re assemble @ Andy's Sept 2019

~~NEW~~ ^{USED} Gear Box put on for Flight back

Home after fly-in with Rodger Conry.

Reason for tail down was ONE IGNITION

Not working. LESLEY had to RE WORK IGNITION

the second time and REPLACE Spark.

Back SEAL WAS leaking some.

Also put on New Starter Elec.