



RECORD OF CONVERSATION

John M. Brannen II
Senior Air Safety Investigator
Central Region

Date: October 8, 2020
Person Contacted: Rene Gonzalez
NTSB Accident Number: CEN20LA415

Narrative:

Spoke with Mr. Gonzalez on the telephone and he confirmed that he was the pilot of N4019V, a Cessna 170 that was involved in an accident on Sept 20, 2020 at San Geronimo Airpark (8T8), near San Antonio, Texas. I asked him to describe what happened and he stated that while landing on runway 35, a gust of wind caused the airplane to drift to the right into the airport perimeter fence. I asked him if there was any mechanical problem and he stated that there weren't any and that it was the gust of wind that blew the airplane to the side. I obtained his e-mail address so that I could send him a NTSB report form to complete.

-----end of entries-----