



MEMORANDUM FOR RECORD

John M. Brannen II
Senior Air Safety Investigator
Central Region

Date: 1/26/2022
NTSB Accident Number: CEN20LA417

Medical and Pathological Information:

An autopsy of the pilot was performed by the Southwestern Institute of Forensic Sciences, Dallas, Texas. The cause of death was blunt force injuries.