



MEMORANDUM FOR RECORD

Dr. David Bowling
Senior Air Safety Investigator
Central Region

Date: December 20, 2020
NTSB Accident Number: CEN21FA026

Medical and Pathological Information

An autopsy of the pilot was performed by the Montgomery County Forensic Services Department, Conroe, Texas. The cause of death was determined as multiple blunt force trauma.

Post-mortem toxicology testing performed by the FAA Civil Aerospace Medical Institute, Bioaeronautical Sciences Research Branch, Forensic Sciences, Oklahoma City, Oklahoma, detected Pheniramine in liver.

David Bowling