

Jenny Archer

From: [REDACTED]
Sent: Tuesday, March 16, 2021 1:40 PM
To: Jenny Archer
Subject: FW: 801EC

Thanks,

David

From: Bill Weatherspoon [REDACTED]
Sent: Sunday, March 14, 2021 3:59 PM
To: david [REDACTED]
Subject: 801EC

David,

Besides of course the autopilot and G5, here's the to-do list.

1. Horizon on lower left of pilot's display goes over and replaces the one on the copilot's panel.
2. Will meet with James to discuss remaining options on the pilot's side, ie, the G5 and moving either the altimeter or airspeed indicator to the hole left by the horizon indicator. Also, need to see what the placement options are for the 3100.
3. No mode/function lights work in night mode on anything Garmin, ie, 750, 530, audio panel, or xpnder.
4. Pitch on G500 PFD displays about 5-6° above normal attitude for any current condition, ie, during taxi, level flt, etc
5. Aircraft always tracks left of course, both hdg and nav modes. If you select hdg of 270°, it tracks 267° plus or minus a couple. Assume the 3100 will fix this?
6. You mentioned sending the servos to S-Tech for overhaul, or rebuild?

Call if any of this is confusing. Anyway, I plan to come in early this week just to make sure we're all on the same pages here about what I'm hoping is going to finally get this thing up and working like it's supposed to!

Thanks,

Bill W.