



MEMORANDUM FOR RECORD

Aaron Sauer
Sr. Air Safety Investigator
Central Region

Date: 06/01/21
NTSB Accident Number: CEN21FA207

An autopsy of the pilot was performed by the University of Iowa Hospitals and Clinics, which listed the cause of death as thermal and inhalational injuries. The manner of death is accident.