

National Transportation Safety Board

Office of Aviation Safety

Denver, CO 80239



CEN21FA330

AUTOPSY REPORT SUMMARY

ACCIDENT

Location: Elgin, Minnesota
Date: July 19, 2021
Time: 1600 central daylight time (2100 UTC)
Airplane: Robinson R44 II, Registration No. N44BJ

AUTOPSY REPORT SUMMARY

An autopsy of the pilot was completed at the request of the Wabasha County Medical Examiner, Plainview, Minnesota, and completed by Mayo Clinic, Rochester, Minnesota. The autopsy report was reviewed by the NTSB Investigator-In-Charge. According to the autopsy report, the pilot died as result of blunt force and thermal injuries, and the manner of death was classified as accident.