



MEMORANDUM FOR RECORD

Aaron Sauer
Sr. Air Safety Investigator
Central Region

Date: 12/05/2021
NTSB Accident Number: CEN21FA376

An autopsy of the pilot was performed by the Montgomery County Coroner, Montgomery County, Ohio, which listed the cause of death as multiple blunt force injuries.