



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: November 9, 2020
Person Contacted: Cory Irwin, FAA Flight Standards
NTSB Accident Number: CEN21LA037 – Wabash, Indiana

Narrative:

The pilot informed Inspector Irwin that at the time of the accident he was priming the engine (turning the engine through) in preparation for start-up. He was planning to conduct a local flight.

----- *end of entries* -----