



RECORD OF INFORMATION

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN21LA051

A Federal Aviation Administration inspector from the Denver Flight Standards District Office performed an examination of the airplane. The photos and assessments provided by the inspector confirmed substantial damage occurred to the left wing and engine firewall.