



MEMORANDUM

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN21LA053 – Holden, Missouri

Narrative:

An autopsy of the pilot was performed by the Jackson County Medical Examiner's office in Kansas City, Missouri. The pilot's death was attributed to diffuse thermal and blunt traumatic injuries sustained as a result of the accident.

----- *end of entries* -----