

TELLURIDE RGNL (TEX)(KTEX) 5 W UTC-7(-6DT) N37°57.23' W107°54.53'

9070 B TPA-10484(1414) ARFF Index—See Remarks NOTAM FILE TEX

RWY 09-27: H7111X100 (ASPH-GRVD) S-45, D-89 PCN 35 F/D/X/T

HIRL 0.4% up E

RWY 09: REIL. PAPI(P4L)—GA 3.55° TCH 46'. Thld dsplcd 200'. Rgt tfc.

RWY 27: REIL. PAPI(P4L)—GA 4.0° TCH 40'. Thld dsplcd 200'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 09: TORA-7111 TODA-7111 ASDA-7111 LDA-6911

RWY 27: TORA-7111 TODA-7111 ASDA-7111 LDA-6911

ARRESTING GEAR/SYSTEM

RWY 09: EMAS

RWY 27: EMAS

SERVICE: **FUEL** 100LL, JET A **OX** 1, 2, 3, 4 **LGT** Rwy 27 PAPI lgts unusable byd 2.5 NM due to terrain. **ACTIVATE** HIRL Rwy 09-27, PAPI Rwy 09, and Rwy 27, REIL Rwy 09 and Rwy 27—CTAF. Arpt lighting system emerg use only 0400-1300Z†.

NOISE: Noise abatement procedures in effect. For more information ctc TEX customer svc 970-728-8600.

AIRPORT REMARKS: Attended Apr-Oct 1400-0400Z†, Nov-Mar

1400-0100Z†. Arpt CLOSED 0400-1300Z†. Rising terrain all

quadrants. Arpt on 1000' mesa, strong vertical turbulence in area of

mesa edge. Rwy 09-27 recommended tkf Rwy 27, land Rwy 09 and avoid populated areas. Rwy 09-27 grade -.08 on rwy ends, -1.3 to approximately midpoint then +.75. Glider, hang glider and helicopter ops on and invof arpt. ARFF Index rstd to FAR 139 design groups AI-CIII. Cold temperature airport. Altitude correction required at or below -18C. Air carrier ops during unattended hrs must notify TEX customer svc at 970-728-8603 24 hrs in advance for provision of adequate ARFF personnel. Ldg fee.

AIRPORT MANAGER: (970) 728-8601

DENVER

H-3E, L-9E

IAP, AD

