



RECORD OF CONVERSATION

Aaron M. Sauer
Aviation Accident Investigator
Central Region

Date: January 5, 2021
Person Contacted: Inspector Richard Hudgins – Baton Rouge Flight Standards
RE: CEN21LA072

Narrative:

During a telephone conversation, Inspector Hudgins stated that he and another inspector examined the airplane at the accident site; however, given the field conditions, a subsequent examination at the operator was necessary. At the operator's facility, a visual examination of the engine revealed no anomalies. The engine fuel filter and oil filter were clean and clear of contaminants. Compression was noted on all engine cylinders. It was determined that the magnetos were to be removed and tested at a repair facility.